



SERVICE BULLETIN

No. 299

Piper Aircraft Corporation

Lock Haven, Pennsylvania, U.S.A.

"FAA DOA EA-1 Approved"

May 29, 1969

Subject: Flight Manual Revision

Models Affected: PA-30 Twin Comanche "C"

Serial Numbers Affected: 30-1717, 30-1745 to 30-1930 incl.

Compliance Time: Prior to but not later than the next 100 hours of operation

Purpose: To provide a revised Flight Manual Supplement for aircraft equipment.

Instructions: Remove and destroy existing Flight Manual Supplement #1 (dated July 31, 1968) to Flight Manual Report No. 1515, and insert the Flight Manual Supplement #1 (dated July 31, 1968; revised April 23, 1969) in its place.

Material Required: Flight Manual Supplement #1 (dated July 31, 1968; revised April 23, 1969) to Flight Manual Report No. 1515.

Availability of Parts: Piper Dealer

Material Allowance: Flight Manual Supplement #1 (dated July 31, 1968; revised April 23, 1969) to Piper Flight Manual Report No. 1515.

Labor Allowance: Not applicable

Material Allowance Termination Date: Not applicable

Disposition of Parts in Stock: Not applicable

Disposition of Replaced Parts: See Instructions, above.
